



OHIO VALLEY ELECTRIC CORPORATION

3932 U. S. Route 23
P. O. Box 468
Piketon, Ohio 45661
740-289-7200

WRITER'S DIRECT DIAL NO:

(740) 289-7259

December 6, 2025

Delivered Electronically

Mr. John Logue, Director
Ohio Environmental Protection Agency
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

**Re: Ohio Valley Electric Corporation
Kyger Creek Station
Notification of CCR Rule Information Posting
2025 Annual Fugitive Dust Report**

Dear Mr. Logue:

As required by 40 CFR 257.106(g), the Ohio Valley Electric Corporation (OVEC) is providing notification to the State Director of the Ohio Environmental Protection Agency (OEPA) that the Kyger Creek Station's Annual Fugitive Dust Report, required by 40 CFR 257.80(c), was placed in the facility's Operating Record on December 6, 2025. The report has also been placed on the company's publicly accessible internet site, and can be viewed at: <http://www.ovec.com/CCRCompliance.php> .

If you have any questions, or require any additional information, please call me at (740) 289-7259, or contact Gabriel Coriell at (740) 289-7267.

Sincerely,

A handwritten signature in black ink that reads "Jeremy Galloway". The signature is written in a cursive, flowing style.

Jeremy Galloway
Environmental Specialist

JDG:zsh

Ohio Valley Electric Corporation

KYGER CREEK STATION



ANNUAL CCR FUGITIVE DUST CONTROL REPORT

Prepared By:

Ohio Valley Electric Corporation
3932 U.S. Rt. 23
Piketon, Ohio 45661

December 2025

Table of Contents

1.0 Introduction.....	1
2.0 Facility Description and Contact Information	1
2.1 Facility Information	1
2.2 Contact Information.....	1
2.3 Facility Description	2
3.0 Fugitive Dust Controls	3
4.0 Citizen Complaint Log	4
4.1 Plant Contacts	4
4.2 Follow-up	4
4.3 Corrective Actions and Documentation.....	4
5.0 Plan Assessment	4
6.0 Recordkeeping, Notification and Internet Requirements.....	5
6.1 Recordkeeping.....	5
6.2 Notification.....	5
6.3 Internet Site Requirements	5

1.0 INTRODUCTION

This Annual CCR Fugitive Dust Control Report (Annual Report) has been prepared pursuant to the air criteria of 40 CFR part 257.80. The Annual Report summarizes activities described in the CCR fugitive dust control plan (Plan) and includes the following components: a description of actions taken to control CCR fugitive dust; a record of all citizen complaints; and a summary of any corrective measures taken.

Pursuant to 40 CFR 257.80(c), the initial Annual Report must be completed no later than 14 months after placing the initial Plan in the facility's operating record. The initial Kyger Creek CCR fugitive dust control plan was placed into the operating record on October 19, 2015. This Annual Report addresses the period from October 18, 2024 to October 18, 2025. In accordance with 40 CFR 105(g)(2), the Annual Report is deemed complete when it is placed in the facility's operating record as described in Section 6.0. The deadline for completing subsequent Annual Reports is one year after the date of completing the previous report.

The Annual Report will be placed in the operating record and retained in the office of the Kyger Creek Station Plant Environmental Manager (PEM). The Plan will also be placed on the Ohio Valley Electric Corporation's (OVEC's) publicly accessible internet website titled "CCR Rule Compliance Data and Information" as described in Section 6.0.

2.0 FACILITY DESCRIPTION AND CONTACT INFORMATION

2.1 Facility Information

General Information:

Name of Facility: Kyger Creek Station

Street: 5758 State Route 7 North

City: Cheshire State: Ohio ZIP Code: 45620

County: Gallia

Latitude: 38°54'57.07" Longitude: 82°07'46.53"

2.2 Contact Information

Facility Operator:

Name: Ohio Valley Electric Corporation

Mailing Address: P.O. Box 468

Physical Address: 3932 US Route 23

City, State, Zip Code: Piketon, Ohio 45661
Telephone Number: 740-289-7200
Email address: CCRCCompliance@ovec.com

Facility Owner:

Name: Ohio Valley Electric Corporation
Mailing Address: P.O. Box 468
Physical Address: 3932 US Route 23
City, State, Zip Code: Piketon, Ohio 45661

Plan Contact:

Name: Kyger Creek Station Plant Environmental Manager (PEM)
Address: 5758 State Route 7 North
City, State, Zip Code: Cheshire, Ohio 45620
Telephone number: 740-367-5050

2.3 Facility Description

The Kyger Creek Power Plant is located on the shore of the Ohio River at Cheshire, Ohio, and consists of five 217 megawatt electric generating units. Each year approximately 2.5 million tons of coals per year are converted to electricity at the Kyger Creek Station, powering homes, businesses, schools, and industrial facilities.

The generation of electricity using coal as a fuel source produces fly ash, boiler slag, and synthetic gypsum. The Kyger Creek Station is equipped with multiple pieces of environmental control equipment used to collect these materials. See the Plan for a further description of plant activities and fugitive dust controls.

3.0 FUGITIVE DUST CONTROLS – 40 CFR 257.80(b)(1)

The following fugitive dust control measures were utilized during the period addressed by this Annual Report:

Plant Activity	Fugitive Dust Control Measures
Plant and Landfill Roadways	Roadways were watered as needed, trucks were tarped and speed control measures were continued. In addition, a wheel wash is located at the Stackout Pad area.
Landfill – unloading and placement of material	Unloading emissions were controlled by maintaining moisture in the material, taking precautionary measures (minimizing drop height) and watering as needed; spreading and compacting emissions were controlled by maintaining vehicle speed, maintaining moisture in the material, and watering as needed.
Landfill – wind erosion	Wind erosion control measures for open areas included: precautionary measures such as minimizing the amount of open area; compacting material as it was unloaded; maintaining moisture content of the materials, watering as needed, and placement of intermediate or permanent cover material.
Fly Ash Pond	Fly Ash Pond site conditions, road conditions, and work activities will be monitored for potential dusty conditions. Dust control measures will be implemented as needed. Corrective measures will consist of but are not limited to, increased water application, wheel washing as needed, decreased operating speeds for trucks and equipment, or ceasing selective activities during high wind conditions.
Boiler Slag Pond	Boiler Slag Pond site conditions, road conditions, and work activities will be monitored for potential dusty conditions. Dust control measures will be implemented as needed. Corrective measures will consist of but are not limited to, increased water application, wheel washing as needed, decreased operating speeds for trucks and equipment, or ceasing selective activities during high wind conditions.
Gypsum, FGD WWTP gypsum Filter Cake, Boiler Slag, and Fly Ash Conveyor Transfer	Emissions were controlled by: using $\frac{3}{4}$ enclosed conveyors and fully enclosed transfers; minimizing drop height from stacker to pile; inherent moisture; and precautionary measures for the pile. Emissions from the loading of trucks were controlled by the moisture of the material, tarping the trucks and by minimizing the drop height into the trucks.

Note: *According to the Station's Title V Air Permit and due to safety concerns, implementation of control measures will not be necessary for roadways that are covered with snow and/or ice or if sufficient precipitation occurs to minimize or eliminate fugitive dust. Implementation of any control measures may be suspended if unsafe or hazardous driving conditions would be created by its use.*

4.0 CITIZEN COMPLAINT LOG – 40 CFR 257.80(B)(3)

4.1 Plan Contacts

Generally, complaints made to the plant are by telephone and received by the PEM (Plan Contact). In the case of holiday, weekends, or other times when the PEM may not be onsite, the plant guard houses or plant general phone number may receive complaint information by telephone that is provided to the PEM as soon as practicable. Complaints may also be made via email at CCRCCompliance@ovec.com or to Ohio EPA who in turn will contact the PEM.

During the period addressed by this report, Kyger Creek Station received one complaint, detailing a potential fugitive dust issue around the facility's Dry Ash Silo. The Ohio Environmental Protection Agency (OEPA) contacted Kyger Creek Station to schedule an on-site visit to observe the area and discuss the complaint.

4.2 Follow-up

As described in the Plan, all complaints will be entered into a log by the PEM with details noted such as the nature of the complaint, date, time, and other relevant details. All complaints will be investigated which may include: checking plant operations at the time of the event, reviewing inspection records, discussing with other plant personnel, reviewing weather data, collecting samples and contacting the person making the complaint to obtain additional information.

As part of Kyger Creek Station's investigation into the issue raised, a careful review of the site's fugitive dust inspection reports was conducted to determine if there were any days on which fugitive dust issues were noted at the silo area or any issues noted around the area. Based on that review, no issues were documented. OEPA and Kyger Creek personnel walked the silo area down, reviewed the related documentation, and discussed the complaint. After the document review and site observations, it was determined that fugitive dust is not an issue for the site, nor has an observation been made that it leaves our facility boundary at any location. This was determined to be an isolated event. Kyger Creek will continue to focus energy on maintaining the site in a manner that prevents and controls fugitive dust.

4.3 Corrective Action and Documentation

Corrective actions will be taken as needed and documented. If it is determined that the Plan needs to be amended as a result of the corrective actions, it will be amended in accordance with 40 CFR 257.80(b)(6). If possible, the PEM will follow-up with the complainant and/or Ohio EPA to explain the findings of the complaint investigation, corrective actions or sampling results. Citizen complaints will be recorded in the Annual Report.

No corrective actions were necessary at the time of receipt of the public complaint. This was determined to be an isolated event. Should issues of this nature arise or continue, corrective actions would align with those fugitive dust controls detailed in the facility's fugitive dust control plan, and likely would include corrective action as detailed in section 3.0 above.

5.0 PLAN ASSESSMENT – 40 CFR 257.80(B)(4)

The Plan will be periodically assessed to verify its effectiveness, and if necessary, amended.

OVEC reviewed the inspection records when preparing this Annual Report to assess the effectiveness of the Plan and determined that no additional or modified measures were warranted.

The fugitive dust plan has been reviewed and is found to be sufficient.

6.0 RECORDKEEPING, NOTIFICATION and INTERNET REQUIREMENTS – 40 CFR 257.80(d)

6.1 Recordkeeping – 40 CFR 257.105(g)

The Annual Report and the Plan (and any subsequent amendment of the plan) will be kept in the facility's operating record as they become available. The Plan and files of all related information will be maintained in a written operating record at the facility for at least five years following the date of each occurrence, measurement, maintenance, corrective action, report, record or study. Only the most recent Plan must be maintained in the record. Files may be maintained on a computer or storage system accessible by a computer.

6.2 Notification – 40 CFR 257.106(g)

The Director of the Ohio EPA and Ohio EPA-SEDO will be notified within 30 days of when the Annual Report is placed in the operating record and on the publicly available internet site. This notification will be made before the close of business on the day the notification is required to be completed. “Before the close of business day” means the notification must be postmarked or sent by e-mail. If the notification deadline falls on a weekend or federal holiday, the notification is automatically extended to the next business day.

6.3 Internet Site Requirements – 40 CFR 257.107(g)

The most recent Annual Report will be placed on the facility’s CCR website titled “CCR Rule Compliance Data and Information” within 30 days of placing it in the operating record.